

Service Letter

Service Letter No. 436 May, 1995


SUBJECT: Slave Piston, P/N 014664

MODELS AFFECTED: C317, C317A, 317B, 317C and 310A


The pocket in the slave piston, P/N 014664, was originally added to reduce the height of the adjusting screw and eliminate possible cover interference (see Fig. A below). Recent investigation has revealed that this potential interference does not and never has existed; therefore, the pocket has been removed (see Fig. B below).

The slave piston, P/N 014664, will remain the same and both new and former parts can be used interchangeably.

This is a product improvement and not subject to campaign.



Former Design
Fig. A



Current Design
Fig. B

**Slave Piston
P/N 014664**