



Service Letter

Service Letter No. 440 June, 1995

SUBJECT: Model 349A Check Valves with White Dot Markings

MODELS AFFECTED: 349A

In October 1994, Jacobs began identifying the Model 349A Check Valve Group, P/N 019957, with a white dot on top of the check valve body assembly. This indicates that the group conforms to critical specifications.

If it becomes necessary to replace the check valve group during repair or maintenance of the Model 349A, make sure that the replacement body assembly is marked with a white dot. Return any new, unmarked Check Valve Groups, P/N 019957, to your Jacobs Warehouse Distributor for credit.

Also, be sure that any Model 349A kits in inventory have the marked check valves. Any kits or housings in inventory which do not have marked check valves may have the valves changed. Return the old, unmarked, unused Check Valve Groups, P/N 019957, to your Jacobs Warehouse Distributor for credit.

Jacobs will stop marking the check valves at the end of 1995.

This is a Jacobs product improvement and not subject to campaign.