



Service Letter No. EX5 September, 1994

Subject: Cast Machined Elbow Next to Turbo

Models Affected: Extarder™ Models EXB59 and EXC83

It is acceptable to clamp the **cast machined elbow** directly to the turbo end without the gasket. This direct connection may become necessary when the clamp will not span the three elements. The mating surfaces must be flat (within 0.004" - 0.006") and must be free of defects which would prevent effective sealing.

Deleting the gasket should not affect performance of the Extarder™.

SERVICE LETTER